

Technical Appendix 10.2: Heritage Assets within the Inner Study Area

Technical Appendix 10.2: Heritage Assets within the Inner Study Area

This Technical Appendix (TA) provides details on the heritage assets recorded in the Inner Study Area¹ identified through desk-based assessment and field survey, together with an assessment of their heritage sensitivity.

This appendix should be read in conjunction with EIA **Chapter 10: Cultural Heritage (EIA Volume 1)**, Section 10.4: Baseline Conditions and Section 10.5: Assessment of Effects. The locations, and extents, of the recorded heritage assets are shown on **Figure 10.1 (EIA Volume 2)**.

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
1	Ardveich, sheepfold	n/a	262200	724480	Historic maps; Aerial photography; Field survey	<p>A rectangular sheepfold is depicted on the 1st edition Ordnance Survey map (Perthshire XCIII 1867) to the southeast of Ardveich township, orientated northwest-southeast. The boundary wall extending from the settlement abuts the north corner and southeast wall.</p> <p>The sheepfold is visible on modern aerial photography (Google Earth, Bing Maps).</p> <p>Field survey recorded the sheepfold in fair condition, comprising turf and stone walls overlain by a later drystone boundary wall to the northeast and overgrown with dense bracken. It measures up to 31 m northwest-southeast. A rectangular structure is situated within the southwest side, 24 m WNW-ENE by 6 m with walls of tumbled stone and an entrance to the ESE.</p>	Low
2	Ardveich, township	1805	262090	724520	HER; Canmore; Historic maps; Aerial photography; Bibliographical sources; Field survey	<p>The HER and Canmore entries record an area of depopulation, consisting of the foundations of about fifteen rectangular buildings, a corn-drying kiln and associated enclosures, at Ardveich. The buildings vary in size from 23 m by 6 m to 9 m by 4 m, with walls up to 1 m high. There are probably two periods of occupation. (Source: Ordnance Survey 1968).</p> <p>The lands surrounding Ardveich, and Dalveich to the west, were the property of the Clan Laurin during the 13th century, evidenced by the fealty of 'Lorn of Ardbechey' in the Ragman Roll of 1296 (poms.ac.uk). The lands later passed into the ownership of the Stewarts of Ardvorlich, who settled at Dalveich from the 17th century (stewartsofbalquhidder.com).</p> <p>Both townships are named on Pont's 1614 map (21(2)), flanking the mouth of Glen Beich.</p> <p>A township, comprising three roofed, four unroofed buildings, two enclosures, a sheepfold and a head-dyke is depicted on the 1st edition Ordnance Survey map (1867). By the time of the 2nd edition Ordnance Survey map (1901), all seven buildings are shown as unroofed, and the enclosures and sheepfold have been removed. The township is no longer named, with the name of Ardveich attributed to the steading to the west (Wester Ardveich). No change is shown by the time of the 1940 Ordnance Survey map.</p> <p>The footings of at least twelve rectangular buildings are visible on modern aerial photography (Google Earth, Bing Maps) to the south of a head-dyke orientated northwest-southeast.</p> <p>Field survey recorded fourteen drystone buildings, two enclosures, a dyke and a field wall, including all features depicted on the 1st edition Ordnance Survey map. They comprise:</p> <p>(a): Rectangular building, 9 m north-south by 5 m with walls up to 1 m wide and 0.3 m high (262067, 724507)</p> <p>(b): Irregular enclosure, 19 m north-south by 15 m, stone-walled abutting west of building (a), less distinct towards watercourse. Entrance to NNE side (262057, 724511)</p> <p>(c): Rectangular building, 17 m north-south by 5 m with walls 1 m wide and 0.5 m high. Three compartments and two entrances on the east side (262063, 724530)</p> <p>(d): Rectangular building, 17 m east-west by 6 m with walls 0.75 m to 1 m wide and 0.75 m high. Three compartments and two entrances on the south side. East end has been terraced into the slope (262062, 724557)</p> <p>(e): Rectangular building, 22 m east-west by 6 m with walls 1 m wide and 0.75 m high. Three compartments and three entrances on the south side. Terraced into south-facing slope (262033, 724586)</p> <p>(f): Rectangular building, 13 m northwest-southeast by 6 m with poorly preserved walls. Possible annex, 3 m by 3 m to middle of northeast side. Enclosure wall (g) abuts to south linking to building (h) (262026, 724574)</p>	Medium

¹ Inner Study Area: the Proposed Development red line boundary (the Site) forms the study area for the identification of heritage assets that could receive direct effects arising from the construction of the Proposed Development.

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>(g) Sub-square enclosure, 25 m east-west by 24 m, linking two buildings (f and h) and forming western limit of settlement. Wall measures 1 m wide and 0.75 m high to west (262026, 724560)</p> <p>(h): Rectangular building, 17 m NNE-SSW by 6 m with walls 1 m wide and 0.5 m high. Possibly formed of two structures separated by entrance to enclosure (g). Three compartments with two entrances on the ESE side (262038, 724548)</p> <p>(i): Rectangular building, 14 m north-south by 6 m with wall footings 1 m wide and 0.2 m high. Two compartments and two entrances on the east side (262047, 724535)</p> <p>(j): Enclosure dyke surrounding the eastern side of settlement (a-i) as depicted on the 1st edition OS map. Wall measures 1 m to 1.5 m wide and 0.75 m high between NGR: 262077, 724570 and 262074, 724503)</p> <p>(k): Rectangular building, 19 m northwest-southeast by 5 m with walls up to 1 m wide and 0.5 m high. Three compartments and two entrances on the southwest side. Possible stone-filled kiln at southeast end indicated by more substantial walls (262078, 724517)</p> <p>(l): Rectangular building, 18 m northwest-southeast by 6 m with walls up to 1 m wide and 0.4 m high. Northeast wall overlies and incorporates the earlier dyke (2j). Three compartments and only one clear entrance to the southwest (262097, 724522)</p> <p>(m): Rectangular building, 11 m north-south by 6 m with wall footings 1 m wide and 0.3 m high. Structure overlies earlier dyke (2j). Possible opposing entrances in east and west walls (262112, 724514)</p> <p>(n): Robbed rectangular building, 25 m northwest-southeast by 6 m with walls 2 m wide and 0.6 m high. Three possible entrances on the southwest side (262118, 724500)</p> <p>(o): Rectangular building, 10 m NNW-SSE by 5 m with walls up to 1 m wide and 0.5 m high. Single compartment with entrance in the ENE side (262104, 724495)</p> <p>(p): Roughly T-shaped wall footings, 30 m north-south with tranverse extent 40 m southeast-northwest along southern base of slope. Wall measures 0.5 m wide and 0.1 m high (262118, 724458)</p> <p>(q): Rectangular building, 11 m north-south by 6 m with walls 1 m wide and 0.2 m to 0.6 m high. Single compartment with external platform or structure, 2 m by 2 m on north side. Possible entrances to east and west (262156, 724480)</p> <p>(r): Rectangular building, 11 m NNW-SSE by 7 m with walls 1 m wide and 0.2 m high. Poorly preserved with no clear entrance (262167, 724472)</p> <p>The features are generally in fair condition with frequent stone infilling of compartments.</p>	
3	Ardveich, cup marked rock	346828	262081	724532	Canmore; Field survey	<p>The Canmore entry records that at the northwest edge of the deserted settlement of Ardveich, an outcrop bears a single cup mark measuring 75 by 40 mm (source: Currie 2005).</p> <p>Field survey recorded the cup mark as described, atop an outcrop of quarried bedrock in good condition.</p>	Medium
4	Ardveich, building	9027	262088	724567	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a building situated on the northern edge of the deserted settlement of Ardveich.</p> <p>The 1st edition Ordnance Survey map (1867) depicts a rectangular enclosure or unroofed structure at this location, rounded at its northwest end and abutting the head-dyke. It has been removed by the time of the 2nd edition Ordnance survey map (1901).</p> <p>The remains are not clearly visible on modern aerial photography (Google Earth, Bing Maps).</p> <p>Field survey recorded the probable enclosure in poor condition at the northeast corner of an enclosure dyke (2j), 13 m ESE-WNW by 7 m and comprising turf banks 0.3 m high. Possibly a former building robbed and overlain by the dyke.</p>	Low
5	Ardveich, trackway		262037	724522	Field survey	<p>Field survey recorded a slight terrace up to 3 m wide across the south-facing slope of a pasture field to the southwest of Ardveich, flanked by stone dumping. It appears to run through metal gate posts within the field and becomes clearer to the southeast. It measures over 200 m northwest-southeast and runs to the southwest side of the deserted settlement at enclosure (2a), continuing between the buildings to (2n and 2o), becoming indistinct.</p>	Negligible

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
6	Ardveich, stone dumps		261945	724560	Field survey	A number of recent stone dumps are scattered across the south-facing slope of a pasture field to the southwest of Ardveich. Frequent large boulders indicate that much of the clearance is modern, although earlier field clearance may be present. The dumps occupy wet areas of ground to the north and south of a relict trackway to the deserted settlement.	Low
7	Ardveich, possible burial		262187	724450	Field survey	Field survey recorded a possible robbed cairn indicated by frequent small stones placed on a bedrock knoll to the southeast of Ardveich settlement. A single orthostat is secured near the high point, possibly within a cut hollow. The knoll measures 15 m northwest-southeast by 9 m and 1.5 m high.	Low
8	Ardveich, sheepfold	344	262090	724670	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records that the remains of a sheepfold lie to the north of the deserted settlement of Ardveich.</p> <p>The 2nd edition Ordnance Survey map depicts a large sub-rectangular sheepfold with five compartments, situated at the head of the burn that runs through Ardveich. It is also depicted on the 1940 Ordnance Survey map.</p> <p>The remains of the sheepfold are visible, though overgrown, on modern aerial photography (Google Earth, Bing Maps). They appear to be reached by a modern track and may have been altered by recent use.</p> <p>Field survey recorded the sheepfold in poor condition, densely overgrown with bracken and comprising principally of fenced compartments with concrete flooring and no clear relict banks. It has been in recent use.</p>	Negligible
9	Ardveich, clearance cairns	345	262160	724650	HER; Canmore; Historic maps; Aerial photography; Field survey	<p>The HER and Canmore entries record that six piles of stones which lie upon an exposed southwest-facing slope have been interpreted as stone clearance heaps, associated with the nearby deserted settlement. They average 4 m in length by 2.5 m.</p> <p>The cairns are visible on modern aerial photography (Google Earth, Bing Maps), distributed in two groups to the north and southeast of the recorded location, between a large sheepfold and the head-dyke of Ardveich.</p> <p>Field survey recorded six cairns across the slope in fair condition, comprising:</p> <p>(a): 5 m diameter and 0.5 m high on steep southwest-facing slope (262182, 724619)</p> <p>(b): 8 m northeast-southwest by 6 m and 0.6 m high on steep southwest-facing slope (262186, 724635)</p> <p>(c): 6 m NNW-SSE by 5 m and 0.7 m high surrounding a massive boulder (262133, 724748)</p> <p>(d): 7 m northeast-southwest by 5 m and 0.7 m high, revetted on downslope (SW) side (262144, 724693)</p> <p>(e): 4.5 m diameter and up to 0.8 m deep; infilled square pit or quarry (262118, 724650)</p> <p>(f): 6 m diameter and 0.6 m high (262140, 724654)</p>	Low
10	Ardveich, cup and ring markings	65788	262129	724866	HER; Canmore; Field survey	<p>The HER and Canmore entries record the location of cup marked rocks at the north edge of a rocky knoll, 500 m northeast of Ardveich farmhouse (source: Currie 2005). They comprise a shelf with seven cups; five at 35 by 12 mm, one at 30 by 10 mm and one at 45 by 12 mm.</p> <p>Field survey identified the cup marks in fair condition and as described. Nearby bedrock has been quarried probably for the construction of the drystone wall (12) below and rock art may have been more extensive. No ring marks were visible.</p>	Medium
11	Ardveich, field wall	9016	262065	725255	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a field boundary to the north of the deserted settlement of Ardveich.</p> <p>The 1st edition Ordnance Survey map (1867) depicts the boundary as a continuation of the eastern limit of the field system at Ardveich, orientated northwest-southeast. It runs for over 550 m from NGR: 262083, 724926 to terminate within woodland on the east bank of the Beich Burn. It remains visible on later maps.</p> <p>The linear wall is visible on modern aerial photography (Google Earth, Bing Maps) and is bisected by a modern track.</p> <p>Field survey recorded the drystone wall in fair to good condition within rough pasture, though it has been truncated by a modern track crossing to the east of a woodland plantation. It survives up to 1 m wide and 0.8 m high along the north side of the woodland.</p>	Low
12	Ardveich, field wall	9017	262097	724870	HER; Historic maps; Aerial	The HER entry records a substantial field boundary to the northwest of the deserted settlement of Ardveich.	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
					photography; Field survey	The 1st edition Ordnance Survey map (1867) depicts the boundary, orientated southwest-northeast from Wester Ardveich, terminating to the north of Ardveich township, where it meets the eastern boundary of the field system (9016). It remains visible on later maps. The linear wall is visible on modern aerial photography (Google Earth, Bing Maps) running for more than 300 m. Field survey recorded the drystone wall in fair condition, 1 m wide and up to 0.6 m high.	
13	Ardveich, dyke	9018	262238	724796	HER; Historic maps; Aerial photography; Field survey	The HER entry records the intermittent and vestigial footings of a dyke running south from a field wall (9017) to meet the head-dyke of Ardveich. The field boundary is not shown on historic maps. A curvilinear field bank is visible for over 230 m within rough pasture on modern aerial photography (Google Earth, Bing Maps), linking to the irregular boundaries (9023) marked by individual standing trees to the south. Field survey recorded the boundary in fair condition, comprising a substantial turf and stone bank 2.5 m wide and 0.7 m high with a ditch on the east side, 1 m wide and 0.5 m deep. To the north it becomes a line of stones, branching to the north and northeast within a gully, before meeting the boundary wall (12).	Low
14	Ardveich, dam	9019	262196	724775	HER; Historic maps; Aerial photography; Field survey	The HER entry records a rudimentary dam, comprising a spread of boulders crossing a gully to the north of Ardveich. Nothing is depicted at the location on historic maps. The spread of stones is visible on modern aerial photography (Google Earth, Bing Maps) along the course of a field bank (9018). Field survey identified a spread of stones at the location, along the course of a curvilinear turf and stone bank (13) but no watercourse was observed. It is possible that the stones once blocked a gully within the contours to the northeast, but its function is unclear.	Low
15	Ardveich, dyke	9020	262366	724494	HER; Historic maps; Aerial photography; Field survey	The HER entry records a dilapidated dyke, frequently comprising an intermittent spread of boulders, to the east of Ardveich. An irregular field boundary is depicted on the 1st edition Ordnance Survey map (1867) forming an inverted L-shape to the east of the township of Ardveich. It is not shown on the 2nd edition map Ordnance Survey map. The north-south extents forming the east and west sides of boundary are visible on modern aerial photography (Google Earth, Bing Maps). The eastern side is visible directly to the south of an existing pylon. Field survey recorded the boundary in poor condition, as a rough alignment of boulders 1.2 m wide and 0.5 m high, running through rough ground and woodland up the south-facing slope. Along the western extent it incorporates a natural north-south shelf of bedrock for much of its course.	Low
16	Ardveich, railway embankment		262245	724380	Historic maps; Aerial photography; Field survey	The 1906 Ordnance Survey map depicts the line of the Lochearnhead, St Fillans and Comrie Railway, opened at the turn of the 20th century along the north shore of Loch Earn. It is shown as a footpath on modern maps. The railway embankment is visible as a tree-lined footpath on modern aerial photography (Google Earth, Bing Maps). Field survey observed that the earthwork embankment is 5 m to 8 m wide and 1.8 m high, with a footpath surfaced with tarmac atop.	Low
17	Ardveich, clearance cairn	9021	262337	724508	HER; Aerial photography; Field survey	The HER entry records a large clearance cairn, 6 m in diameter, marked by a mature oak tree growing from its centre. The tree marking the cairn is visible on modern aerial photography (Google Earth, Bing Maps) enclosed by relict field banks to the east of Ardveich. Field survey recorded as described and situated on a more level part of the south-facing slope, up to 1 m high.	Low
18	Ardveich, dyke	9022	262230	724555	HER; Historic maps; Aerial	The HER entry records a low intermittent dyke running a zig-zag course uphill to the northwest, turning sharply to the northeast at the given NGR.	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
					photography; Field survey	<p>The irregular field boundary is not depicted on historic maps.</p> <p>A zig-zag of turf and stone boundaries is visible on modern aerial photography (Google Earth, Bing Maps) to the east of Ardveich.</p> <p>Field survey recorded irregular extents of turf bank running along and across the contours of the southwest-facing slope. At the eastern end they surround an area above a wet hollow, with a northwestern spur extending atop a break of slope or slight terrace. The banks measure 1.3 m wide and 0.3 m to 0.5 m high.</p>	
19	Ardveich, dyke	9023	262265	724586	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a short extent of dyke running parallel to the north end of an irregular boundary (9022).</p> <p>The field boundary is not depicted on historic maps.</p> <p>Turf and stone boundaries are visible on modern aerial photography (Google Earth, Bing Maps) to the east of Ardveich.</p> <p>Field survey recorded irregular extents of turf bank running along and across the contours of the southwest-facing slope. At the eastern end they surround an area above a wet hollow, with a northwestern spur extending atop a break of slope or slight terrace. The banks measure 1.3 m wide and 0.3 m to 0.5 m high.</p>	Low
20	Ardveich, dyke	9024	262284	724550	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a sinuous dyke following the contour from the given NGR to 262281, 724594, to the north of a large irregular boundary (9020) to the east of Ardveich.</p> <p>The field boundary is not depicted on historic maps.</p> <p>Turf and stone boundaries are visible on modern aerial photography (Google Earth, Bing Maps) to the east of Ardveich.</p> <p>Field survey did not identify a bank at the location referenced, though the entry is likely to correspond to the southern end of a curvilinear boundary (13).</p>	Low
21	Ardveich head-dyke	9025	262289	724388	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a well-maintained dyke, a continuation of the head-dyke along the north of Ardveich settlement, forming the southern boundary of a woodland plantation to the east.</p> <p>The boundary is depicted on the 1st and 2nd edition Ordnance Survey maps.</p> <p>The field wall is visible on modern aerial photography (Google Earth, Bing Maps), in use as a modern boundary.</p> <p>Field survey observed that the drystone wall overlies the earlier boundary for the majority of its course. Where any slight deviation was indicated, dense bracken precluded inspection of the earlier course. The wall measures 0.7 m wide and 0.8 m high in good condition.</p>	Low
22	Ardveich, rig and furrow	9026	262242	724388	HER; Aerial photography; Field survey	<p>The HER entry records a small area of rig and furrow cultivation, measuring 20 m northwest-southeast by 10 m, immediately to the north of the head-dyke at Ardveich, to the east of a large sheepfold.</p> <p>Possible furrows are faintly visible on modern aerial photography (Google Earth, Bing Maps), orientated NNW-SSE.</p> <p>Field survey observed parallel drainage channels cut down the slope and no rig and furrow was identified. The ground is steep and stony rough pasture with no regular evidence of cultivation.</p>	Negligible
23	Ardveich, cup marking	65786	261860	724821	HER; Canmore; Field survey	<p>The HER and Canmore entries record the location of a cup marked rock to the north of Ardveich, one of a pair in close proximity (source: Currie 2005). It comprises an outcrop in rough pasture, 300 m north-northeast of Ardveich farmhouse; one cup, 55 by 28 mm.</p> <p>Field survey recorded the cup mark as described in poor condition, slightly irregular with a sub-rectangular base, near the centre of a probable erratic boulder.</p>	Medium
24	Ardveich, cup marking	65787	261780	724858	HER; Canmore; Field survey	<p>The HER and Canmore entries record the location of a cup marked rock to the north of Ardveich; one of a pair in close proximity (source: Currie 2005). It comprises a boulder, 3 m by 1.5 m and 0.8 m high, with at least three cups. Two at east end measure 45 by 12 mm, and one on west end measures 50 by 18 mm.</p> <p>Field survey recorded the cup marks in poor condition; very shallow. Four are closely grouped to the northeast end of a large erratic, with two possible cups near the centre and two to three possible cups at the southeast end.</p>	Medium

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
25	Ardveich, track		262020	724620	Historic maps; Aerial photography; Field survey	<p>The 1st edition Ordnance Survey map (1867) depicts a track leading from Ardveich township, orientated northwest-southeast towards the loch shore at Woodend Cottage, and to the north up Glen Beich.</p> <p>The track is visible on modern aerial photography (Google Earth, Bing Maps), though it is overgrown and truncated in places by a modern track.</p> <p>Field survey recorded an extent of the track to the north of the settlement, comprising a hollow-way in poor condition, 3 m wide and up to 1 m deep on the upslope (northeast) side. It is flanked by banks 2 m wide and 0.5 m high, extending northwest-southeast from where it remains in use as a quad track.</p>	Negligible
26	Ardveich, field wall	9035	261910	725074	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a field wall to the north of Wester Ardveich, to the east of the Beich Burn.</p> <p>The 1st edition Ordnance Survey map (1867) depicts a field boundary forming part of the subdivisions to the north of Ardveich and Wester Ardveich farmsteads. The boundary extends for over 700 m to the north of Wester Ardveich and meets the northern end of the eastern boundary wall (9016). A continuation (9036) on the north side of the eastern boundary extends from slightly to the west of this terminus.</p> <p>The linear wall is visible on modern aerial photography (Google Earth, Bing Maps), though partially obscured by woodland to the north.</p> <p>Field survey confirmed that the drystone wall survives in good condition, overgrown with bracken, 0.8 m wide and up to 1 m high.</p>	Low
27	Ardveich, field wall	9036	262010	725513	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records a field wall to the north of Wester Ardveich, to the east of the Beich Burn.</p> <p>The 1st edition Ordnance Survey map (1867) depicts a continuation of the field boundary from Weaster Ardveich (9035), orientated north-south for 350 m and terminating at a tributary of the Beich Burn. By the time of the 2nd edition Ordnance Survey map (1901), a spur wall extends northeast from NGR: 262010, 725513 to a sheepfold 130 m away.</p> <p>The linear wall is visible on modern aerial photography (Google Earth, Bing Maps).</p> <p>Field survey confirmed that the drystone wall survives in good condition, overgrown with bracken, 0.8 m wide and up to 1 m high.</p>	Low
28	Ardveich, quarried bedrock		262008	724712	Field survey	<p>Field survey recorded a possible small quarry, comprising a low cut in the south-facing slope to the north of Ardveich, measuring 5 m north-south by 3 m and 0.4 m deep. Several thin slabs of stone were observed below the hollow, though no obvious toolmarks were noted.</p>	Negligible
29	Ardveich, clearance cairn		261955	725197	Field survey	<p>Field survey recorded a sub-circular pile of large stones, obscured by bracken to the south of a woodland plantation. The clearance measures 5 m east-west by 4 m and 1 m high.</p>	Low
30	Ardveich, clearance cairn		261956	725182	Field survey	<p>Field survey recorded a sub-circular pile of large stones, gathered at the edge of a slight terrace, to the south of a woodland plantation. The clearance measures 5 m east-west by 4 m and 1 m high.</p>	Low
31	Ardveich, clearance cairn		262011	725102	Field survey	<p>Field survey recorded an irregular pile of field boulders dragged to a collection point around a bedrock knoll, to the south of a woodland plantation. The clearance measures 7 m in diameter and 0.4 m high.</p>	Low
32	Ardveich, clearance cairn		262031	725116	Field survey	<p>Field survey recorded a sub-circular mound of turf-covered stones, to the south of a woodland plantation. The cairn measures 7 m east-west by 6 m and 0.8 m high, with a possible arc of upright stones lining the southwest edge. It is more overgrown and weathered than nearby features.</p>	Low
33	Ardveich, clearance cairn		262041	725084	Field survey	<p>Field survey recorded an oval pile of field boulders dragged to a collection point, to the south of a woodland plantation. The clearance measures 7 m northeast-southwest by 3 m and 0.5 m high.</p>	Low
34	Ardveich, clearance cairn	9028	262020	725084	HER; Aerial photography; Field survey	<p>The HER entry records the location of a clearance cairn, the easternmost in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded.</p> <p>The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone.</p> <p>Field survey recorded the cairn of large stones in good condition, measuring 5 m northeast-southwest by 4 m and 0.6 m high.</p>	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
35	Ardveich, clearance cairn	9029	262005	725092	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded. The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn as a scatter of boulders in good condition, measuring 8 m east-west by 4 m and 0.7 m high.	Low
36	Ardveich, clearance cairn	9030	261995	725090	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded. The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of large stones in good condition, measuring 5 m east-west by 4 m and 0.7 m high.	Low
37	Ardveich, clearance cairn	9031	261975	725089	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded. The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn as a tumble of large boulders in good condition, measuring 8 m east-west by 5 m and 1.2 m high.	Low
38	Ardveich, clearance cairn	9032	261963	725082	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, the westernmost in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded. The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of large stones in good condition, measuring 8 m east-west by 5 m and 1 m high.	Low
39	Ardveich, ditch		261956	725045	Field survey	Field survey recorded a sinuous ditch running westward downslope for 30 m from NGR: 261987, 725046 to the given NGR. Rough boulders are piled on the south side forming an irregular bank. The ditch measures up to 1.5 m wide and 0.6 m deep.	Low
40	Ardveich, clearance cairn	9033	262005	725026	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in an arc of five cairns orientated east-west, to the west of a modern track. No further details are recorded. The arc of cairns is faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of boulders in good condition, measuring 6 m southeast-northwest by 5 m and 1 m high, focused around a bedrock knoll.	Low
41	Ardveich, clearance cairn	9037	262015	724997	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in a group of five cairns, to the west of a modern track. No further details are recorded. The cairns are faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of boulders in good condition, measuring 6 m southeast-northwest by 5 m and 1.2 m high.	Low
42	Ardveich, clearance cairn	9034	262085	724990	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in a group of five cairns, to the west of a modern track. No further details are recorded. The cairns are faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of stones in good condition, measuring 10 m southeast-northwest by 6 m and 1 m high.	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
43	Ardveich, clearance cairn	9038	261963	724966	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in a group of five cairns, to the west of a modern track. No further details are recorded. The cairns are faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of mixed size stones in good condition, measuring 8 m northeast-southwest by 6 m and 0.6 m high, within a hollow in the west-facing slope.	Low
44	Ardveich, clearance cairn	9039	261915	724980	HER; Aerial photography; Field survey	The HER entry records the location of a clearance cairn, situated in a group of five cairns, to the west of a modern track. No further details are recorded. The cairns are faintly visible on modern aerial photography (Google Earth, Bing Maps), comprising overgrown mounds of stone. Field survey recorded the cairn of mixed size stones in good condition, measuring 7 m northwest-southeast by 6 m and 0.6 m high.	Low
45	Ardveich, clearance cairn		261884	724928	Field survey	Field survey recorded an irregular, low collection of stones measuring 3.5 m in diameter and 0.2 m high, at the base of a tree. The stones are mixed in size and indicative of field clearance.	Low
46	Ardveich, sheepfold		262150	725540	Historic maps; Aerial photography; Field survey	The 1st and 2nd edition Ordnance Survey maps depict a five-compartmented sheepfold between the Beich Burn and a track leading north from Ardveich. By the time of the 2nd edition Ordnance Survey map (1901), a linear field boundary extends to the east and west of the sheepfold. The wall to the east continues for 1.3 km to terminate on the east side of the Allt Bhacaidh. The sheepfold, adjacent to a modern track, and the walls are visible on modern aerial photography (Google Earth, Bing Maps). Field survey recorded the sheepfold in good condition with turf-capped drystone walls surviving up to 1.25 m high and featuring two lintelled sheep 'creeps' to the southeast compartment. A wooden post and wire enclosure abuts the north side.	Low
47	Ardveich, possible platform		262284	725892	Field survey	Field survey recorded a possible sub-rectangular platform indicated by a concentration of stones, measuring 5 m northeast-southwest by 3.5 m, on an otherwise featureless west-facing slope. Possible alignments of stones were noted on the western edge and the platform may have provided the foundation for a temporary shieling hut. The stones have been disturbed by recent tree planting.	Negligible
48	Ardveich, dyke	9001	262373	726100	HER; Historic maps; Aerial photography	The HER entry records the location of a curvilinear dyke to the east of the Beich Burn, comprising a single course of boulders and a ditch. No boundary is shown on historic maps. No remains are visible on modern aerial photography (Google Earth, Bing Maps) within rough pasture. Field survey recorded a turf and stone dyke in poor condition, appearing as a drainage cut in peat 0.8 m wide and 0.2 m deep, lined with stones on the southwest side. It runs intermittently for 100 m southeast-northwest from the given NGR to terminate at a tree-lined gully.	Negligible
49	Ardveich, shieling		262377	726294	Field survey	Field survey recorded a probable rectangular shieling within rough pasture, comprising a turf bank surrounding a stone-filled depression with a possible entrance to the west side. It measures 4 m northwest-southeast by 3 m and 0.4 m high in fair condition.	Low
50	Ardveich, shieling		262502	726317	Field survey	Field survey recorded the remains of a probable sub-circular shieling, comprising a stoney knoll overgrown with bracken in rough pasture. It measures 5 m in diameter and 0.5 m high, in fair condition with a well-defined central hollow.	Low
51	Ardveich, shieling	9002	262407	726458	HER; Historic maps; Aerial photography; Field survey	The HER entry records the location of a possible shieling to the east of the Beich Burn. No structures are depicted on historic maps. The structure is not visible on modern aerial photography (Google Earth, Bing Maps) within dense bracken coverage.	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						Field survey recorded the rectangular structure in fair condition above the south bank of a tributary to the Beich Burn, measuring 4 m north-south by 3 m and 0.3 m high. There is no clear entrance within the low turf and stone bank.	
52	Ardveich, shieling	9003	262447	726506	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records the location of a possible shieling to the east of the Beich Burn.</p> <p>No structures are depicted on historic maps.</p> <p>The structure is not visible on modern aerial photography (Google Earth, Bing Maps) within dense bracken coverage.</p> <p>Field survey recorded the rectangular structure in fair condition above the north bank of a tributary to the Beich Burn, measuring 5 m northeast-southwest by 3 m with boulder walls 0.6 m wide and 0.3 m high. There is a possible entrance in the northwest side.</p>	Low
53	Ardveich, shieling	9004	262407	726549	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records the location of a possible shieling to the east of the Beich Burn.</p> <p>No structures are depicted on historic maps.</p> <p>The structure is not visible on modern aerial photography (Google Earth, Bing Maps) within dense tree and bracken coverage.</p> <p>Field survey recorded the rectangular structure in fair condition above the north bank of a tributary to the Beich Burn, measuring 8 m NNE-SSW by 4 m with drystone walls 0.6 m wide and 0.4 m high. Two possible entrances were noted in the WNW side. A modern deer fence overlies the southern end.</p>	Low
54	Ardveich, sheepfold	9005	262370	726640	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records the location of a sheepfold to the east of the Beich Burn.</p> <p>No structures are depicted on historic maps.</p> <p>The stone footings of a rectangular structure are visible on modern aerial photography (Google Earth, Bing Maps), orientated north-south within rough pasture.</p> <p>Field survey recorded the structure in good condition, measuring 14 m north-south by 5 m with drystone walls 0.8 m wide surviving up to 1.3 m high. An entrance is formed in the middle of the east wall, 0.8 m wide. No internal divisions were noted.</p>	Low
55	Ardveich, building	9006	262407	726644	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records the location of a possible sheepfold to the east of the Beich Burn.</p> <p>No structures are depicted on historic maps.</p> <p>A rectangular structure is possibly visible on modern aerial photography (Google Earth, Bing Maps), orientated north-south within rough pasture.</p> <p>Field survey recorded a probable house in good condition, measuring 17 m north-south by 6 m with drystone walls 1 m wide surviving up to 0.6 m high. An entrance is formed towards the south end of the east side. The construction uses larger stones with internal dividing walls and no capping stones on the footings.</p>	Low
56	Ardveich, sheepfold	9007	262415	726673	HER; Historic maps; Aerial photography; Field survey	<p>The HER entry records the location of a possible sheepfold to the east of the Beich Burn.</p> <p>No structures are depicted on historic maps.</p> <p>No remains are visible on modern aerial photography (Google Earth, Bing Maps), within rough pasture to the north of a tributary to the Beich Burn.</p> <p>Field survey recorded a rectangular structure in fair condition above the north bank of a gully within dense bracken. It measures 16 m north-south by 6.5 m with drystone walls 1 m wide and 0.6 m high. There may be two internal divisions with a probable entrance to the south end of the west wall. Its construction is indicative of a house and the ends are more rounded than the building to the south.</p> <p>An area of possible rig and furrow cultivation in fair condition lies immediately to the north, orientated east-west with a wavelength of 2 m to 3 m and 0.3 m high, across an area 20 m by 20 m.</p>	Low
57	Ardveich, shieling	9008	262391	726668	HER; Historic maps; Aerial	The HER entry records the location of a possible shieling to the east of the Beich Burn.	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
					photography; Field survey	No structures are depicted on historic maps. No remains are visible on modern aerial photography (Google Earth, Bing Maps), within rough pasture to the north of a tributary to the Beich Burn. Field survey recorded a stone-lined sub-rectangular hollow in fair condition above the north bank of a gully within dense bracken. It measures 6 m north-south by 5 m within a turf bank 1 m wide and 0.5 m high.	
58	Ardveich, field bank		262560	726645	Field survey	Field survey recorded a field boundary in fair condition, comprising a turf bank and alignments of boulders up to 3 m wide and 0.8 m high bordering the eastern side of a group of shielings on the east bank of the Beich Burn. The recorded extent continues for 150 m north and 50 m west of the given NGR. To the west, it comprises a low turf bank 0.3 m high. The northern extent has faint traces of a ditch on the east side and may represent the dyke for an infield at the shieling group.	Low
59	Glen Beich, shielings	5092	262230	727070	HER; Historic maps; Aerial photography; Field survey	The HER and Canmore entries record that the remains of two shieling-huts (at NGR: 262400, 727200 and NGR: 262230, 727070) are visible on oblique aerial photography (RCAHMSAP 2000) to the east of Beich Burn. The shielings are visible on modern aerial photography (Google Earth, Bing Maps), situated within rough pasture. Field survey was not able to visit the southwestern shieling which was inaccessible due to dense bracken overgrowth. The northeastern structure was recorded in fair condition, comprising a rectangular turf bank internally lined with stone, 0.7 m wide and 0.4 m high. The structure measures 8 m NNE-SSW by 5 m atop a low knoll and no internal features were noted. An entrance in the WNW side measures 0.5 m wide.	Low
60	Ardveich, enclosure		262735	727152	Field survey	Field survey recorded a ruined drystone enclosure constructed within a steep-sided gully and bisected by a burn. The structure measures 20 m ENE-WSW by 12 m with drystone walls 0.5 m wide and 0.7 m high, in places revetted into the valley slopes. No internal features were noted, and a wooden post and corrugated sheeting were discarded in the interior. Further stretches of ruined revetting wall lie 15 m to the southwest and to the east at NGR: 262798, 727167. These extents measure 15 m in length along the south bank of the burn and probably represent a land boundary incorporating one or more enclosures along its course.	Negligible
61	Glen Beich, shielings	4858; 257118	262940	727845	HER; Canmore; Historic maps; Aerial photography; Field survey	The HER and Canmore entries record that a group of at least six sub-rectangular shieling huts are visible on oblique aerial photography (RCAHMSAP 2000) on the east bank of Beich Burn. Four huts are depicted on the current edition of the Ordnance Survey 1:10000 map (1977). The shielings are not depicted on historic maps. A line of three sub-rectangular structures is visible on modern aerial photography (Google Earth, Bing Maps), orientated northeast-southwest at the recorded location. An additional structure is visible 100 m to the north. Field survey recorded sixteen rectangular shieling structures in fair condition and one field wall across the area, comprising: (a): 8 m northeast-southwest by 4.5 m with turf and stone walls 0.8 m wide and 0.5 m high. Entrance 0.5 m wide to southeast @ 262940, 727845; (b): 5 m northeast-southwest by 3 m with tumbled turf and stone walls 0.6 m high. Probable entrance to northwest @ 262932, 727831; (c): 6 m northeast-southwest by 4.5 m with tumbled turf and stone walls 0.6 m high. Cellular sunken interior with entrance to southwest and upper compartment to northwest @ 262953, 727856; (d): 7 m NNE-SSW by 4 m with turf and stone walls 0.7 m wide and 0.3 m high, damaged by recent forestry planting. Probable entrance to SSW @ 262910, 727860; (e): 5 m ENE-WSW by 4.5 m with sub-triangular boulder perimeter 0.8 m wide and 0.5 m high. No clear entrance @ 262918, 727871; (f): 8 m north-south by 4 m with turf and stone walls 0.8 m wide and 0.5 m high. Entrance to east @ 262902, 727900;	Medium

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>(g): 4 m by 4 m with turf and stone walls 0.8 m wide and 0.4 m high. Probable entrance to north @ 262895, 727901;</p> <p>(h): L-shaped boulder alignment on steeper ground to northwest of shielings, 8 m NNW-SSE by 7 m ENE-WSW, 0.7 m wide and 0.3 m high @ 262887, 727908;</p> <p>(i): 5 m east-west by 4 m with turf and stone walls 1 m wide and 0.9 m high. Entrance 0.7 m wide to east @ 262894, 727885;</p> <p>(j): 8 m north-south by 5 m with turf and stone walls 0.8 m wide and 1 m high, revetted into natural slope. Entrance to east @ 262816, 727853;</p> <p>(k): 5 m northeast-southwest by 4 m with turf and stone walls 1 m high revetted into natural slope. Entrance to west @ 262832, 727845;</p> <p>(l): 4 m north-south by 3.5 m with turf and stone walls 0.6 m wide and 0.5 m high. No clear entrance @ 262832, 727853;</p> <p>(m): 4.5 m northeast-southwest by 3.5 m with irregular large stone tumble 0.3 m high. Probable entrance to southwest @ 262792, 727807;</p> <p>(n): 100 m north of main group (a-d), 7 m NNW-SSE by 6 m with turf and stone walls 1 m wide and 0.8 m high, revetted into the natural slope. Probable entrance to southeast @ 262934, 727960;</p> <p>(o): 8 m north-south by 4 m with turf and stone walls 0.9 m wide and 0.6 m high. Entrance 0.4 m wide to east @ 262928, 727957;</p> <p>(p): Sub-rectangular patch of reeds, 4 m east-west by 3 m with turf-covered stones indicative of structure, 0.3 m high @ 263055, 727934;</p> <p>(q): 8 m east-west by 4 m with drystone walls 0.5 m wide and 0.5 m high atop reed-covered knoll @ 263021. 727900.</p>	
62	Glen Beich, building	4858; 257121	263065	728105	HER; Canmore; Historic maps; Aerial photography; Field survey	<p>The HER and Canmore entries record the location of a building on the south bank of a tributary east of the Beich Burn.</p> <p>A square unroofed structure is depicted on the 2nd edition Ordnance Survey map. It is also shown on the 1940 Ordnance Survey map.</p> <p>The remains of a rectangular drystone building are visible on modern aerial photography (Google Earth, Bing Maps), orientated northeast-southwest.</p> <p>Field survey recorded the structure in good condition, measuring 7 m northeast-southwest by 4 m with drystone walls 0.9 m wide and 1.4 m high. The entrance is 1 m from the southwest end, 0.55 m wide.</p>	Low
63	Glen Beich, shieling		263054	728116	Field survey	Field survey recorded a sub-rectangular robbed shieling, measuring 5 m northeast-southwest by 3.5 m with turf and stone walls 1.5 m wide and 0.4 m high. The structure has no clear entrance and is crossed by a modern deer fence.	Low
64	Glen Beich, structure		263046	728140	Field survey	Field survey recorded the remains of a sunken drystone structure in fair condition, measuring 7 m east-west by 4.5 m with walls 1.5 m wide and 1 m high, revetted into the south-facing slope of a valley east of the Beich Burn. The structure is cellular, with bowed walls cut into the slope and almost shamrock-shaped in plan.	Low
65	Glen Beich, structure		263018	728153	Field survey	Field survey recorded the remains of a rectangular structure in fair condition with two phases. The first structure measures 12 m northwest-southwest by 5.5 m with drystone walls 1 m wide and 0.6 m high. It is overlain by a later structure 8 m by 5.5 m with an entrance to the southeast.	Low
66	Glen Beich, shieling		263004	728160	Field survey	Field survey recorded a small possible shieling, measuring 4 m northeast-southwest by 3 m with turf banks 1 m wide and 0.5 m high. A possible entrance lies in the centre of the northwest side. The structure is sub-rectangular in plan and in poor condition.	Low
67	Glen Beich, shielings		263090	728182	Field survey	Field survey recorded the remains of a rectangular turf and stone shieling (a) in poor condition, measuring 8 m northeast-southwest by 4 m with walls 0.6 m wide and 0.3 m high. No clear entrance was noted. The structure is	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>situated on a gentle west-facing slope within better draining ground to the east of the Beich Burn, close to a number of grouped shielings.</p> <p>A second structure (b) lies 20 m to the north, measuring 4 m north-south by 3.5 m with turf and stone walls 1 m wide and 0.3 m high. A possible entrance was noted in the east and west sides.</p>	
68	Glen Beich, shieling		263038	728240	Field survey	Field survey recorded the remains of a probable rectangular shieling in fair condition on the southwest periphery of a group of shielings to the east of the Beich Burn. It measures 4 m northwest-southeast by 3 m with turf and stone walls 0.8 m wide and 0.3 m high.	Low
69	Glen Beich, shielings	4858; 257120	263100	728280	HER; Canmore; Historic maps; Aerial photography; Field survey	<p>The HER and Canmore entries record that the remains of at least three shieling huts are visible on oblique aerial photography (RCAHMSAP 2000) to the east of Glen Beich. Two lie to the south of an unnamed stream and are depicted on the current edition of the OS 1:10000 map (1977); the third and a possible fourth lie to the north of the unnamed stream.</p> <p>No structures are depicted on historic maps.</p> <p>The remains of four rectangular drystone structures are visible on modern aerial photography (Google Earth, Bing Maps).</p> <p>Field survey recorded eight turf and stone structures in good condition close to the stream, comprising:</p> <p>(a): Rectangular structure 6 m NNE-SSW by 4 m with stone-faced interior walls 0.8 m wide and 0.8 m high. Probable entrance to ENE @ 263037, 728268;</p> <p>(b): Rectangular structure 5 m north-south by 4 m with walls 1 m wide and 0.4 m high. Probable entrance to east @ 267034, 728274;</p> <p>(c): Rectangular structure 8 m north-south by 5 m with stone walls 1 m wide and 0.5 m high @ 263032, 728289;</p> <p>(d): Rectangular drystone structure 8 m NNE-SSW by 4.5 m with walls 1 m wide and 0.5 m high. Possible entrance to WNW @ 263075, 728251;</p> <p>(e): Cellular structure revetted into slope, 4 m northeast-southwest by 4 m with walls 0.8 m wide and 0.6 m high. Two cells with probable entrance to northwest @ 263070, 728260;</p> <p>(f): Oval drystone structure revetted into slope, 4 m northwest-southeast by 4 m with walls 0.8 m wide and 0.6 m high. Probable entrance to north @ 263089, 728255;</p> <p>(g): Rectangular drystone structure, 7 m WNW-ENE by 4 m with walls 1 m wide and 0.6 m high. Entrance 0.5 m wide to SSW @ 263100, 728280;</p> <p>(h): Drystone structure, 4.5 m ENE-WSW by 4 m with walls 1 m wide and 0.8 m high. Entrance to ENE @ 263091, 728288.</p>	Medium
70	Glen Beich, shielings				Field survey	<p>Field survey recorded the remains of eleven turf and stone structures situated on the northwest-facing slope flanked by two burns between Glen Beich and Glen Tarken. The structures are in fair to poor condition and comprise:</p> <p>(a): Rectangular stone footings, 8 m east-west by 4.5 m with walls 1 m wide and 0.4 m high. Possible entrance to east @ 263785, 728655;</p> <p>(b): Rectangular structure, 8 m northwest-southeast by 4 m with turf and stone walls 1 m wide and 0.5 m high. Probable entrance to southeast, abutting offshoot wall lining north bank of burn and continuing for 35 m to southeast @ 263722, 728689;</p> <p>(c): Rectangular structure, 7 m northwest-southeast by 4 m with turf and stone walls 1 m wide and 0.3 m high. No clear entrance @ 263698, 728708;</p> <p>(d): Sub-rectangular structure, 5 m north-south by 4 m with western wall continuing 8 m north, possibly forming second structure or enclosure on north side. Turf and stone walls measure 1 m wide and 0.4 m high @ 263670, 728651;</p>	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>(e): Square structure, 4 m northwest-southeast by 4 m with turf and stone walls 0.6 m wide and 0.3 m high. Entrance to northwest @ 263687, 728650;</p> <p>(f): Sub-rectangular structure, 4 m north-south by 3 m with unclear turf and stone walls @ 263698, 728582;</p> <p>(g): Rectangular structure, 6 m east-west by 4 m with turf and stone walls 1 m wide and 0.3 m high, overgrown by reeds @ 263727, 728500;</p> <p>(h): Rectangular structure, 6 m NNE-SSW by 4 m with turf and stone walls 1 m wide and 0.3 m high. Possible entrance to ESE @ 263717, 728500;</p> <p>(i): Rectangular structure, 7m northeast-southwest by 4 m with tumbled stone walls 1 m wide and 0.5 m high @ 263608, 728596;</p> <p>(j): Rectangular structure abutting northwest of (i), 7 m northwest-southeast by 5 m with tumbled stone walls 1 m wide and 0.6 m high. Probable entrance to northwest @ 263606, 728600;</p> <p>(k): Square hollowed structure, 2.5 m by 2.5 m area of tumbled stones 0.4 m high @ 263597, 728603.</p>	
71	Glen Beich, sheepfold		263920	728850	Modern maps; Historic maps; Aerial photography; Field survey	<p>The modern 1:25000 Ordnance Survey map depicts a compartmented sheepfold and enclosure to the east of a modern track, reached by a track spur.</p> <p>The sheepfold is not depicted on historic maps.</p> <p>The modern sheepfold is visible on modern aerial photography (Google Earth, Bing Maps).</p> <p>Field survey recorded that the sheepfold comprises a concrete floored core with wooden fenced paddocks and a dipper. Modern enclosures surround the complex which does not appear in recent use. No earlier elements or features were observed.</p>	Negligible
72	Glen Beich, shielings		264341	729226	Field survey	Field survey recorded two sub-square turf and stone shielings on a well-drained knoll within rough pasture to the west of Glen Tarken. They each measure 4 m by 4 m upstanding to 0.4 m high with central hollows, in fair to poor condition.	Low
73	Glen Beich, marker cairn		264520	729210	Field survey	Field survey recorded a small marker cairn atop better draining pasture, comprising an isolated collection of angular stones 2.5 m in diameter and 0.5 m high.	Low
74	Glen Beich, possible shieling		264426	729737	Field survey	Field survey recorded the possible remains of a shieling comprising rectangular stone footings 6 m northwest-southeast by 4 m up to 0.2 m high, enclosing a group of reeds atop a knoll.	Low
75	Glen Beich, possible structure		264878	729965	Field survey	Field survey recorded an area of stones atop a low knoll, measuring 2 m northeast-southwest by 1 m and 0.3 m high, possibly indicating the poorly preserved remains of a marker cairn or small structure.	Low
76	Glen Beich, settlement		265140	730495	Field survey	<p>Four unroofed structures are depicted on the 2nd edition Ordnance Survey map on the south bank of the Allt Coire an Daimh, a tributary of the Beich Burn.</p> <p>The remains of the structures are visible on modern aerial photography (Google Earth, Bing Maps). Two possible structures are also visible to the north of the burn.</p> <p>Field survey recorded eleven rectangular structures, an enclosure and a turf bank in fair condition on the south side of the burn. They comprise:</p> <p>(a): Rectangular building 5 m east-west by 4 m with drystone walls 1 m wide and 0.8 m high. An enclosure abuts the north side, 6 m north-south by 6 m with an entrance to the east @ 265107, 730472;</p> <p>(b): 4 m NNE-SSW by 3 m with turf walls 1 m wide and 0.4 m high. Possible entrance to ENE @ 265100, 730484;</p> <p>(c): Rectangular structure 9 m SSE-NNW by 5 m with a 3 m long entrance passage at the north end. Turf and stone walls 1.2 m wide and up to 0.75 m high. Sunken into knoll with possible entrance to ENE @ 265117, 730492;</p> <p>(d): Rectangular structure abutting south end of (c), 7 m NNW-SSE by 4 m with walls 1.2 m wide and 0.8 m high. Entrance to SSE end of ENE wall @ 265120, 730487;</p>	Medium

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>(e): Sunken structure on east face of knoll, 7 m east-west by 4 m. Hollow 0.6 m deep with entrance joining to the building (c) to the west side @ 265122, 730493;</p> <p>(f): Similar to (e), sunken hollow 4 m by 4 m and 0.6 m deep, abutting eastern side of building (d) @ 265126, 730488;</p> <p>(g): Turf footings, 4 m east-west by 4 m and 0.6 m high with entrance to east @ 265133, 730505;</p> <p>(h): Narrow turf and stone structure, 5 m north-south by 3.5 m with walls 0.6 m wide and 0.3 m high. Probable entrance to south @ 265126, 730515;</p> <p>(i): Turf bank 20 m northeast-southwest by 2 m wide and 0.6 m high @ 265120, 730520;</p> <p>(j): Rectangular drystone building, 10 m northwest-southeast by 6 m with walls surviving to 0.75 m in places. Interior filled with tumble @ 265140, 730493;</p> <p>(k): Drystone structure at southeast end of (j), 5 m by 4 m and 0.5 m high, with entrance to northeast @ 265145, 730487;</p> <p>(l): Turf and stone enclosure bank enclosing a low-lying area 9 m by 9 m, with interior stone face surviving up to 1 m high Entrance to west @ 265156, 730475;</p> <p>(m): Rectangular drystone building, 7 m NNE-SSW, with walls 0.6 m wide surviving to 1.3 m high. Entrance to ESE @ 265156, 730465.</p>	
77	Glen Tarken, clearance cairn		265017	728950	Field survey	Field survey recorded an oval pile of stones, 4 m northwest-southeast by 3 m and 0.5 m high within rough pasture towards the head of Glen Tarken. A second, smaller grouping of turf covered stones may be 10 m to the northeast.	Low
78	Glen Tarken, shielings		265210	729015	Field survey	Field survey recorded the remains of two rectangular structures in fair condition flanking a burn at the head of Glen Tarken. To the east of the burn (a), the stone footings of a shieling 6.5 m WNW-ESE by 3.5 m survive with walls 0.7 m wide and 0.4 m high. The second structure (b) lies 20 m to the northwest, measuring 4 m by 4 m and up to 0.3 m high, defined by a turf and stone bank around a reed-grown hollow.	Low
79	Glen Tarken, shooting butts		266300	728770	Field survey	Field survey encountered several shooting butts in fair condition, frequently aligned in rows and evenly spaced northeast-southwest. One group (a-c) was recorded towards the head of the valley on the southwest-facing slope distributed 40 m to 70M apart, SSW from given NGR. They comprise slightly curved or crescent walls of turf or turf-covered stone, 2 m to 3 m long and up to 1.3 m high, supported by wooden posts.	Low
80	Glen Tarken, shooting butts		266568	728881	Field survey	Field survey recorded two shooting butts in good condition, spaced 40 m apart down the southwest-facing slope of the valley, comprising turf and stone walls 3 m long and 1 m wide, up to 1 m in height and reinforced with wooden posts. Additional modern wood stances lie to the southwest, but no further features were observed to the northeast.	Low
81	Creag Ruadh, marker cairn		267416	729255	Field survey	Field survey recorded a small marker cairn, comprising a low, circular collection of stones atop the highest of bedrock knolls at Creag Ruadh. It measures 1 m in diameter and 0.5 m high.	Low
82	Glen Tarken, shooting butts		267647	727407	Field survey	Field survey encountered several shooting butts in fair condition, frequently aligned in rows and evenly spaced northeast-southwest. One group (a-h) was recorded on the southwest-facing slope distributed 40 m apart, southwest from given NGR. They comprise square or U-shaped structures of turf-covered stone, 4 m a side and up to 1 m high, often supported by wooden posts. Some have been augmented with wooden screens. Two further examples (i and j) lie close to the top of the slope at NGR: 267891, 727595 in fair condition.	Low
83	Meall Reamhar, marker cairn		267986	727640	Field survey	Field survey recorded a small marker cairn, situated atop the high point of a knoll above the southwest-facing slope of Glen Tarken. It comprises a low circular mound of stones, 2.5 m in diameter and 0.4 m high. A slight turf perimeter bank indicates the removal of the topsoil to provide a level surface for the cairn.	Low
84	Glen Tarken, shielings		268170	727075	Field survey	Field survey recorded a group of four shielings and two buildings, in fair condition, to the southeast of a rocky knoll on the south-facing slope of Glen Tarken. They comprise: (a): Rectangular building 8 m east-west by 4.5 m with drystone walls 1 m wide and 0.6 m high. Entrance to south @ 270317, 726960;	Low

Asset No	Asset Name	HER No / NRHE No	Easting	Northing	Source	Description	Sensitivity
						<p>(b) Rectangular footings, 5 m northeast-southwest by 3 M with drystone walls 1 m wide and 0.4 m high. Situated 12 m to the southeast;</p> <p>(c): Possible arc of earthfast stones, forming footings 2.5 m in diameter and 0.5 m high. Wall dimensions are unclear, situated 5 m to the west;</p> <p>(d): D-shaped enclosure utilising natural cliff of bedrock as north wall, measuring 7 m ESE-WNW by 4 m with an entrance to the south in a curving wall of stones 0.8 m high. Situated 25 m to the northwest;</p> <p>(e): Possible rectangular footings, 5 m northeast-southwest by 4 m with turf covered stone walls 1 m wide and 0.3 m high. Situated 30 m southwest;</p> <p>(f): Rectangular drystone building, 8 m ESE-WNW by 4.5 m, with walls 1.2 m wide and 0.4 m high. A massive boulder, 2.6 m high, has seemingly destroyed the structure by rolling into its centre from upslope to the NNE. Tumble and structural lines visible beneath the boulder support this impression. Situated 100 m to the northwest of the core group.</p>	